

LABOR AND MATERIALS

1	Copper	Connection	$\frac{3}{4}$	\$
1	Curb	Cock Valve	$\frac{3}{4}$ in.	\$
1	Service box	Short	$3\frac{1}{2} \times 4\frac{1}{2}$	\$
	Old returned	Long	$4\frac{1}{2} \times 5\frac{1}{2}$	
6	Ft.	Copper	$\frac{3}{4}$ in. Pipe at	\$
				\$
	Nipples		in. at	\$
	Bushings		to in. at	\$
	Red'g	Coupl'gs	to in. at	\$
	Inc'g			
	Union		in. at	\$
	Meter		in. at	\$
				\$
	Compound Joints		at	\$
	Maintenance Foreman			\$
	Hrs. Water Maint. Man	—1	at	\$
	Hrs. Water Maint. Man	—2	at	\$
	Hrs. Garage Foreman		at	\$
	Hrs. Labor		at	\$
	Hrs. Compressor		at	\$
				\$
	Trucking			\$
	Pav't Patch			\$
				\$
				\$
				\$
				\$

DOUGLAS

Ave. No. 25

Name of Owner

Labor and Mat'l. Report OCT. 2 19 81



46 5" 43'

● Curb Box

12" Main

Elev. of Main at tap 5'

Gate at ●

● Gate at

● Curb Box

NEW HOUSE