

Labor and Materials

Copper	}	Connection.....	\$	
Lead				
Curb	}	Cock Valve	}	
		T. S. & V.		in
Service Box	}	Short 3½ x 4½	}	
Old returned		Long 4½ x 5½		
		Buff. or Rdway		
Ft.	}	Copper	} Pipe at	
in.		Galv Iron		
		Cast Iron		
Nipples	in. at		\$	
Bushings	to	in. at	\$	
Red'g	}	Couplings.....to.....	in. at	
Inc'g				
Union.....	in. at		\$	
Meter.....	in. at		\$	
Lead Joints at			\$	
Leadite Joints at			\$	
Hrs. Foreman at			\$	
Hrs. Chauffeur at			\$	
Hrs. Tapper at			\$	
Hrs. Labor at			\$	
Hrs. Labor at			\$	
Hrs. Compressor at			\$	
Compensation Ins.			\$	
Trucking			\$	
Builders Use of Water			\$	
			\$	
			\$	
			\$	
			\$	
			\$	
			\$	
			\$	

St. 31
 Pl.
 Ave. No. 23

Douglas

Name of Owner
Robert Starks Bartlett

Labor and Mat'l. Report 19

● Curb Box

This tap is shut of
 to main hole in
 copper Tee in 1-5-61
 Between main and curb
 Box. Miller.
 Was shut off at Curb box 3-2-56