

LABOR AND MATERIALS

1 Copper } Connection 1" \$
 1 Lead }
 1 Curb } Cock } 1 in. 01-1 seal \$
 } Valve }
 } T. S. & V. }
 1 Service box { Short 3 1/2 x 4 1/2 }
 Old returned { Long 4 1/2 x 5 1/2 }
 { Buff or Rdway } \$
 21 Ft. 1 in. { Copper } Pipe at \$
 { G. I. }
 { G. I. }
 Nipples in. at \$
 Bushings to in. at \$
 Red'g }
 Inc'g } Coupl'gs to in. at \$
 Union in. at \$
 Meter in. at \$
 Lead Joints at \$
 Compound Joints at \$
 Maintenance Foreman \$
 Hrs. Water Maint. Man-1 at \$
 Hrs. Water Maint. Man-2 at \$
 Hrs. Garage Foreman at \$
 Hrs. Labor at \$
 Hrs. Compressor at \$
 Compensation Ins. at \$ per C. \$
 Trucking \$
 Pav't Patch \$
 Tap by Giggord & Co. \$
 9-16-67. \$
 O'head \$
 \$
 \$

St. ~~Pl.~~
Aver. No. 27

Elm
Name of Owner City of Glens Falls
Elm St. Parking Plaza.

Labor and Mat'l. Report Sept. 16 19 67.

