

LABOR AND MATERIALS

1 Copper } Connection 3/4" \$ \_\_\_\_\_  
 Lead }  
 1 Curb } Cock } 3/4 in. ORISAL \$ \_\_\_\_\_  
 } ~~Valve~~ }  
 } ~~S.S.V.~~ }  
 1 Service box } ~~Short 3 1/2 x 4 1/2~~ }  
 Old returned } Long 4 1/2 x 5 1/2 } \$ \_\_\_\_\_  
 } ~~Buff or Rdway~~ }  
 12 Ft. 3/4 in. } Copper } Pipe at \$ \_\_\_\_\_  
 } ~~Curb~~ }  
 } ~~Curb~~ }  
 Nipples \_\_\_\_\_ in. at \$ \_\_\_\_\_  
 Bushings \_\_\_\_\_ to \_\_\_\_\_ in. at \$ \_\_\_\_\_  
 Red'g }  
 Inc'g } Coupl'gs \_\_\_\_\_ to \_\_\_\_\_ in. at \$ \_\_\_\_\_  
 Union \_\_\_\_\_ in. at \$ \_\_\_\_\_  
 Meter \_\_\_\_\_ in. at \$ \_\_\_\_\_  
 Lead Joints at \$ \_\_\_\_\_  
 Compound Joints at \$ \_\_\_\_\_  
 Maintenance Foreman \$ \_\_\_\_\_  
 Hrs. Water Maint. Man-1 at \$ \_\_\_\_\_  
 Hrs. Water Maint. Man-2 at \$ \_\_\_\_\_  
 Hrs. Garage Foreman \_\_\_\_\_ at \$ \_\_\_\_\_  
 Hrs. Labor \_\_\_\_\_ at \$ \_\_\_\_\_  
 Hrs. Compressor at \$ \_\_\_\_\_  
 Compensation Ins. at \$ \_\_\_\_\_ per C \$ \_\_\_\_\_  
 Trucking \$ \_\_\_\_\_  
 Pav't Patch \$ \_\_\_\_\_  
TAP BY ST JOHN & CO \$ \_\_\_\_\_  
NOV-16-1976 \$ \_\_\_\_\_  
 O'head \$ \_\_\_\_\_  
 \$ \_\_\_\_\_

St. \_\_\_\_\_  
 Ave. No. 29

EIM

Name of Owner  
Herlihy Property

Labor and Mat'l. Report Nov. 16 1976

13'-8"      16'-5"  
 ● Curb Box

6" Main      Elev. of Main at tap 6'  
 Gate at ●      ● Gate at

● Curb Box

LSM-SC-6-1-67