

LABOR AND MATERIALS

| | |
|--|--------------|
| Copper Lead } Connection | \$ |
| Curb { Clock Valve } | \$ |
| { T. S. & V. } | in. \$ |
| Service box } Short 3 1/2 X 4 1/2 } | \$ |
| Old returned } Long 4 1/2 X 5 1/2 } | \$ |
| { Buff or Rdway } | \$ |
| Ft. <u>3</u> / <u>4</u> in. } Copper } Pipe at | \$ |
| { Galv. Iron } | \$ |
| { Cast Iron } | \$ |
| Nipples in. at | \$ |
| Bushings to in. at | \$ |
| Red'g } Couplings to in. at | \$ |
| Inc'g } | \$ |
| Union in. at | \$ |
| Meter in. at | \$ |
| Lead Joints at | \$ |
| Compound Joints at | \$ |
| Hrs. Foreman at | \$ |
| Hrs. Chauffeur at | \$ |
| Hrs. Tapper at | \$ |
| Hrs. Labor at | \$ |
| Hrs. Labor at | \$ |
| Hrs. Compressor at | \$ |
| Compensation Ins. | \$ |
| Trucking | \$ |
| Builders Use of Water | \$ |
| by Muller & Maguire | \$ |
| | \$ |
| | \$ |
| | \$ |
| | \$ |
| | \$ |
| | \$ |

St. ~~50~~
 Area No. 50

Elm

Name of Owner

Labor and Mat'l. Report June 1945

#50

Tap on Paris St

6" Main

Elev. of Main at tap

Gate at ● ● Gate at

● Curb Box