

LABOR AND MATERIALS

1	Copper	} Connection	1"	\$
	Lead			
1	Curb	} Cock Valve T.S. & V.	3/4 in.	\$
1	Service box	} Short 3 1/2 x 4 1/2 Long 4 1/2 x 5 1/2		\$
	Old returned			
10	3/4 in.	} Copper G. I. C.I.	Pipe at	\$
	Nipples	in. at		\$
	Bushings	to in. at		\$
	Red'g Inc'g	} Coupl'gs	to in. at	\$
	Union	in. at		\$
	Meter	in. at		\$
				\$
	Compound Joints	at		\$
	Maintenance Foreman			\$
	Hrs. Water Maint. Man	1 at		\$
	Hrs. Water Maint. Man	2 at		\$
	Hrs. Garage Foreman	at		\$
	Hrs. Labor	at		\$
	Hrs. Compressor	at		\$
				\$
	Trucking			\$
	Pav't Patch			\$
				\$
				\$
				\$
				\$

ELM

St. ~~Pl.~~
Ave. No. 76

Name of Owner

Labor and Mat'l. Report

July 19 23

ELM
ST



SHERMAN AVE.

6" Main

Elev. of Main at tap 4'

Gate at ●

● Gate at

● Curb Box