

LABOR AND MATERIALS

1	Copper	Connection	$\frac{3}{4}$	\$
	Lead			
1	Curb	Cock Valve	$\frac{3}{4}$ in.	\$
		T.S. & V.		
1	Service box	Short $3\frac{1}{2} \times 4\frac{1}{2}$		
	Old returned	Long $4\frac{1}{2} \times 5\frac{1}{2}$		\$
10	Ft. $\frac{3}{4}$ in.	Copper	Pipe at	\$
		C.I.		
		C.I.		
	Nipples	in. at		\$
	Bushings	to in. at		\$
	Red'g			
	Inc'g	Coupl'gs. to in. at		\$
	Union	in. at		\$
	Meter	in. at		\$
				\$
	Compound Joints	at		\$
	Maintenance Foreman			\$
	Hrs. Water Maint. Man-1	at		\$
	Hrs. Water Maint. Man-2	at		\$
	Hrs. Garage Foreman	at		\$
	Hrs. Labor	at		\$
	Hrs. Compressor	at		\$
				\$
	Trucking			\$
	Pav't Patch			\$
				\$
				\$
				\$
				\$

EMPIRE

Ave. No. 6

Name of Owner

Labor and Mat'l. Report

MAY 14 1926



28' 34'

● Curb Box

Main

Elev. of Main at tap 4'

Gate at ●

● Gate at

● Curb Box