

LABOR AND MATERIALS

1	Copper	} Connection	$\frac{3}{4}$ "	\$
	Lead			
1	Curb	} Cock	$\frac{3}{4}$ in.	\$
1	Service box	} Short $3\frac{1}{2} \times 4\frac{1}{2}$		\$
	Old returned			
15	Ft.	} Copper	$\frac{3}{4}$ in.	\$
	Nipples	in. at		\$
	Bushings	to	in. at	\$
	Red'g	} Coupl'gs	to	in. at
	Inc'g			
	Union	in. at		\$
	Meter	in. at		\$
				\$
	Compound Joints	at		\$
	Maintenance Foreman			\$
	Hrs. Water Maint. Man	1 at		\$
	Hrs. Water Maint. Man	2 at		\$
	Hrs. Garage Foreman	at		\$
	Hrs. Labor	at		\$
	Hrs. Compressor	at		\$
				\$
	Trucking			\$
	Pav't Patch			\$
				\$
				\$
				\$
				\$
				\$

FIELDING St. Ave. No. 6

Name of Owner

Labor and Mat'l. Report SEPT 27 1930



25'2" 21'

● Curb Box

6" Main Elev. of Main at tap 5'

Gate at ● Gate at

● Curb Box