

Labor and Materials

1	Copper Lead	} Connection	3/4"		\$
1	Curb	} Cock } Valve } T. S. & V.	0.11 = 1/8"	in	\$
1	Service Box	} Short 3 1/2 x 4 1/2 } Long 4 1/2 x 5 1/2			\$
	Old returned		} Buff. or Rdway		
26	Ft. 3/4	} Copper } Galv. Iron } Cast Iron		Pipe at	\$
					\$
					\$
	Nipples			in. at	\$
	Bushings			to in. at	\$
	Red'g Inc'g	} Conplings		to in. at	\$
	Union			in. at	\$
	Meter			in. at	\$
	Lead Joints			at	\$
	Leadite Joints			at	\$
	Hrs. Foreman			at	\$
	Hrs. Chauffeur			at	\$
	Hrs. Tapper			at	\$
	Hrs. Labor			at	\$
	Hrs. Labor			at	\$
	Hrs. Compressor			at	\$
	Compensation Ins.				\$
	Trucking				\$
	Builders Use of Water				\$
	Tappby Gifford				
	4-22-68				

St. 19
Pr
Ave. No. 13

Name of Owner
Charles D Thorne

Labor and Mat'l. Report April 22 1968



4" Main Elev. of Main at tap 4'

Gate at ● ● Gate at

● Curb Box

Old Galv service 3/4
Remove 4-22-68
By Gifford