

### Labor and Materials

1	<del>Copper</del> Lead	Connection	$\frac{1}{2}$			\$
1	Curb	Cock Valve T-S & V.	$\frac{3}{4}$	in		\$
1						
24	Ft. $\frac{3}{4}$ in.	Copper Galv Iron Cast Iron	}	Pipe at		\$
	Nipples			in. at		\$
	Bushings			to ..... in. at		\$
	Red'g Inc'g	Conplings		to ..... in. at		\$
			Union		in. at	
	Meter			in. at		\$
	Lead Joints			at		\$
	Leadite Joints			at		\$
	Hrs. Foreman			at		\$
	Hrs. Chauffeur			at		\$
	Hrs. Tapper			at		\$
	Hrs. Labor			at		\$
	Hrs. Labor			at		\$
	Hrs. Compressor			at		\$
	Compensation Ins.					\$
	Trucking					\$
	Builders Use of Water					\$
						\$
						\$
						\$
						\$
						\$
						\$
						\$
						\$

Str. 15  
 Pt. 9  
 Ave. No.

Flandreaux

Name of Owner  
Howard H. Ramsey

Labor and Mat'l. Report DOG. 30 1921

4" Main

Elev. of Main at tap.....

Gate at ● ● Gate at

● Curb Box