

LABOR AND MATERIALS

1	Copper } Connection	$\frac{3}{4}$	\$	
1	Lead } Cock		\$	
1	Curb } Valve	$\frac{3}{4}$ in.	\$	
		F.S. & V.		
1	Service box } Short 3-1/2 x 4-1/2		\$	
	Old returned } Long 4-1/2 x 6-1/2		\$	
8	Ft. $\frac{3}{4}$ in. } Copper		\$	
		Pipe at	\$	
	Nipples	in. at	\$	
	Bushings	to in. at	\$	
	Red'g		\$	
	Inc'g		\$	
	Union	in. at	\$	
	Meter	in. at	\$	
			\$	
	Compound Joints at		\$	
	Maintenance Foreman		\$	
	Hrs. Water Maint. Man - 1 at		\$	
	Hrs. Water Maint. Man - 2 at		\$	
	Hrs. Garage Foreman	at	\$	
	Hrs. Labor	at	\$	
	Hrs. Compressor at		\$	
			\$	
	Trucking		\$	
	Pav't Patch		\$	
			\$	
			\$	
			\$	
			\$	
			\$	

FOWLER

St.

Ave. No.

10

Name of Owner

Labor and Mat'l. Report 1932, MAY 24



31-3

38-3

● Curb Box

6" Main

Elev. of Main at tap

4'

Gate at ●

● Gate at

● Curb Box

NEW HOUSE