

LABOR AND MATERIALS

1	Copper } Connection	3/4	\$
1	Curb } Cock Valve } T.S. & V. }	3/4 in.	\$
1	Service box } Old returned }	Short 2-1/2 x 4-1/2 } Long 4-1/2 x 5-1/2 }	\$
24	Ft. } Copper } Pipe at	3/4 in.	\$
	Nipples	in. at	\$
	Bushings	to in. at	\$
	Red'g		\$
	Inc'g		\$
	Union	in. at	\$
	Meter	in. at	\$
			\$
	Compound Joints at		\$
	Maintenance Foreman		\$
	Hrs. Water Maint. Man - 1 at		\$
	Hrs. Water Maint. Man - 2 at		\$
	Hrs. Garage Foreman	at	\$
	Hrs. Labor	at	\$
	Hrs. Compressor at		\$
			\$
	Trucking		\$
	Pav't Patch		\$
			\$
			\$
			\$
			\$
			\$

FULTON

St. No. 1

Name of Owner

Labor and Mat'l. Report 1934, SEPT. 12



31-0 19-6

● Curb Box

10" Main

Elev. of Main at tap 5 1/2'

Gate at ●

● Gate at

● Curb Box

OLD TAP TO BE DUG UP