

LABOR AND MATERIALS

1	Copper lead } Connection	$\frac{3}{4}$	\$	_____
1	Curb } Cock Valve } F.S. & V.	$\frac{3}{4}$ in.	\$	_____
1	Service box } Old returned	{ Short 3-1/2 x 4-1/2 } { long 4-1/2 x 6-1/2 }	\$	_____
10	Ft. $\frac{3}{4}$ in. } Copper } Sh. } Gal.	Pipe at	\$	_____
_____	Nipples	_____ in. at	\$	_____
_____	Bushings	_____ to _____ in. at	\$	_____
_____	Red'g			_____
_____	Inc'g			_____
_____	Union	_____ in. at	\$	_____
_____	Meter	_____ in. at	\$	_____
_____			\$	_____
_____	Compound Joints at		\$	_____
_____	Maintenance Foreman		\$	_____
_____	Hrs. Water Maint. Man - 1 at		\$	_____
_____	Hrs. Water Maint. Man - 2 at		\$	_____
_____	Hrs. Garage Foreman	_____ at	\$	_____
_____	Hrs. Labor	_____ at	\$	_____
_____	Hrs. Compressor at		\$	_____
_____			\$	_____
_____	Trucking		\$	_____
_____	Pav't Patch		\$	_____
_____			\$	_____
_____			\$	_____
_____			\$	_____
_____			\$	_____
_____			\$	_____

FULTON St. No. 38

Name of Owner BROWN

Labor and Mat'l. Report 19 37, MAY 4



21'-10" 25'

● Curb Box

10" Main

Elev. of Main at tap 5'

Gate at ●

● Gate at

● Curb Box

OLD SHUT OFF