

LABOR AND MATERIALS

1	Copper Lead	Connection	$\frac{3}{4}$	\$	
1	Curb Cock Valve T.S. & V.		$\frac{3}{4}$ in.	\$	
1	Service box Old returned	Short $3-1/2 \times 4-1/2$ Long $4-1/2 \times 5-1/2$		\$	
27	Ft.	$\frac{3}{4}$ in.	Copper Gal. Gal.	Pipe at	\$
	Nipples			in. at	\$
	Bushings			to in. at	\$
	Red'g				
	Inc'g				
	Union			in. at	\$
	Meter			in. at	\$
					\$
	Compound Joints			at	\$
	Maintenance Foreman				\$
	Hrs. Water Maint. Man - 1			at	\$
	Hrs. Water Maint. Man - 2			at	\$
	Hrs. Garage Foreman			at	\$
	Hrs. Labor			at	\$
	Hrs. Compressor			at	\$
					\$
	Trucking				\$
	Pav't Patch				\$
					\$
					\$
					\$
					\$
					\$

GAGE Ave. No. 26
Name of Owner

Labor and Mat'l. Report 1934, OCT. 17



23'-7" 18'

● Curb Box

4" Main Elev. of Main at tap 5 1/2'

Gate at ● Gate at

● Curb Box

SHUT OFF AT MAIN