

LABOR AND MATERIALS

1	Copper } Connection	3/4"	\$
1	Lead } Cock	3/4" in.	\$
	Curb } Valve		
		T.S. & V.	
1	Service box { Short 3-1/2 x 4-1/2		\$
	Old returned { Long 4-1/2 x 5-1/2		\$
11	Ft. 3/4 in. { Copper		\$
		Gal.	
		Gal.	
		Pipe at	\$
	Nipples	in. at	\$
	Bushings	to in. at	\$
	Red'g		
	Inc'g		
	Union	in. at	\$
	Meter	in. at	\$
			\$
	Compound Joints at		\$
	Maintenance Foreman		\$
	Hrs. Water Maint. Man - 1 at		\$
	Hrs. Water Maint. Man - 2 at		\$
	Hrs. Garage Foreman	at	\$
	Hrs. Labor	at	\$
	Hrs. Compressor at		\$
			\$
	Trucking		\$
	Pav't Patch		\$
			\$
			\$
			\$
			\$
			\$
			\$

GAGE

15

Ave. No.

Name of Owner

SPALDING

Labor and Mat'l. Report 1938, APR. 5



37'4" 45'3"

● Curb Box

4"

Main

Elev. of Main at tap

4 1/2'

Gate at ●

● Gate at

● Curb Box

NEW HOUSE