

# LABOR AND MATERIALS

1 Copper } Connection <sup>3/4</sup> \$ \_\_\_\_\_  
 -Lead }  
 1 Curb } Cock Valve } <sup>3/4</sup> in. \$ \_\_\_\_\_  
 T.S. & V. }  
 1 Service box { Short 3-1/2 x 4-1/2 } \$ \_\_\_\_\_  
 Old returned { Long 4-1/2 x 5-1/2 }  
 10 Ft. <sup>3/4</sup> in. { Copper } Pipe at \$ \_\_\_\_\_  
 Nipples \_\_\_\_\_ in. at \$ \_\_\_\_\_  
 Bushings \_\_\_\_\_ to \_\_\_\_\_ in. at \$ \_\_\_\_\_  
 Red'g \_\_\_\_\_  
 Inc'g \_\_\_\_\_  
 Union \_\_\_\_\_ in. at \$ \_\_\_\_\_  
 Meter \_\_\_\_\_ in. at \$ \_\_\_\_\_  
 \_\_\_\_\_ \$ \_\_\_\_\_  
 Compound Joints at \$ \_\_\_\_\_  
 Maintenance Foreman \$ \_\_\_\_\_  
 Hrs. Water Maint. Man - 1 at \$ \_\_\_\_\_  
 Hrs. Water Maint. Man - 2 at \$ \_\_\_\_\_  
 Hrs. Garage Foreman \_\_\_\_\_ at \$ \_\_\_\_\_  
 Hrs. Labor \_\_\_\_\_ at \$ \_\_\_\_\_  
 Hrs. Compressor at \$ \_\_\_\_\_  
 \_\_\_\_\_ \$ \_\_\_\_\_  
 Trucking \_\_\_\_\_ \$ \_\_\_\_\_  
 Pav't Patch \_\_\_\_\_ \$ \_\_\_\_\_  
 \_\_\_\_\_ \$ \_\_\_\_\_  
 \_\_\_\_\_ \$ \_\_\_\_\_  
 \_\_\_\_\_ \$ \_\_\_\_\_  
 \_\_\_\_\_ \$ \_\_\_\_\_

GAGE

Ave. No. 17

Name of Owner  
FRED NARROW

Labor and Mat'l. Report 1937, MAY 8



● Curb Box

6" Main

Elev. of Main at tap 5'

Gate at ● Gate at

TAX ID # 302.16-12-33

● Curb Box

OLD SHUT OFF