

LABOR AND MATERIALS

Copper } Connection _____ \$
 Lead }
 Curb } Cock _____ in. _____ \$
 } Valve _____
 } T.S. & V. _____
 Service box { Short 3-1/2 x 4-1/2 } _____ \$
 Old returned { Long 4-1/2 x 5-1/2 } _____
 10 Ft. 3/4 in. { Copper } Pipe at _____ \$
 } _____
 } _____
 Nipples _____ in. at _____ \$
 Bushings _____ to _____ in. at _____ \$
 Red'g _____
 Inc'g _____
 Union _____ in. at _____ \$
 Meter _____ in. at _____ \$
 _____ \$
 Compound Joints at _____ \$
 Maintenance Foreman _____ \$
 Hrs. Water Maint. Man - 1 at _____ \$
 Hrs. Water Maint. Man - 2 at _____ \$
 Hrs. Garage Foreman _____ at _____ \$
 Hrs. Labor _____ at _____ \$
 Hrs. Compressor at _____ \$
 _____ \$
 Trucking _____ \$
 Pav't Patch _____ \$
 _____ \$
 _____ \$
 _____ \$
 _____ \$
 _____ \$

GARFIELD

St. _____
 Ave. No. 29

Name of Owner _____

Labor and Mat'l. Report 1931, MAY 7



27'7" 24'5"

● Curb Box

6" Main

Elev. of Main at tap 5'

Gate at ●

● Gate at

● Curb Box