

LABOR AND MATERIALS

1	Copper Lead	} Connection <u>3/4</u>	\$	
1	Curb Cock Valve T.S. & W.		} _____ in.	\$
1	Service box Old returned	{ Short 3-1/2 x 4-1/2 Long 4-1/2 x 5-1/2 }		\$
6	Ft. <u>1</u> "	{ Copper G.I. Gal. }	Pipe at _____	\$
	Nipples _____			in. at _____
	Bushings _____	to _____	in. at _____	\$
	Red'g			
	Inc'g			
	Union _____	in. at _____	\$	
	Meter _____	in. at _____	\$	
			\$	
	Compound Joints at _____		\$	
	Maintenance Foreman _____		\$	
	Hrs. Water Maint. Man - 1 at _____		\$	
	Hrs. Water Maint. Man - 2 at _____		\$	
	Hrs. Garage Foreman _____	at _____	\$	
	Hrs. Labor _____	at _____	\$	
	Hrs. Compressor at _____		\$	
			\$	
	Trucking _____		\$	
	Pav't Patch _____		\$	
			\$	
			\$	
			\$	
			\$	

GARFIELD St. 37
 No. 37
 Name of Owner _____

Labor and Mat'l. Report 1924, JUNE 7



35-6 34-6

● Curb Box

6" Main Elev. of Main at tap 4'

Gate at ● ● Gate at

● Curb Box