

LABOR AND MATERIALS

1 Copper } Connection _____ \$
~~Lead~~ }
 1 Curb } Cock _____ \$
 Valve } _____ in. _____ \$
 T.S. & V. }
 1 Service box { Short 3-1/2 x 4-1/2 } _____ \$
 Old returned { Long 4-1/2 x 5-1/2 } _____ \$
 8 Ft. 3/4 in. { Copper } Pipe at _____ \$
 Gal. }
 Gal. }
 _____ Nipples _____ in. at _____ \$
 _____ Bushings _____ to _____ in. at _____ \$
 _____ Red'g _____
 _____ Inc'g _____
 _____ Union _____ in. at _____ \$
 _____ Meter _____ in. at _____ \$
 _____ _____ \$
 _____ Compound Joints at _____ \$
 _____ Maintenance Foreman _____ \$
 _____ Hrs. Water Maint. Man - 1 at _____ \$
 _____ Hrs. Water Maint. Man - 2 at _____ \$
 _____ Hrs. Garage Foreman _____ at _____ \$
 _____ Hrs. Labor _____ at _____ \$
 _____ Hrs. Compressor at _____ \$
 _____ _____ \$
 _____ Trucking _____ \$
 _____ Pav't Patch _____ \$
 _____ _____ \$
 _____ _____ \$
 _____ _____ \$
 _____ _____ \$

REAR OF 34 SHERIDAN

St. _____
 GARFIELD Pl. No. 43 P
 Ave. No. _____

Name of Owner _____

Labor and Mat'l. Report 1931, APR. 23



15'8" 29'3"

● Curb Box

GARFIELD ST

6" Main

Elev. of Main at tap 5'

Gate at ● ● Gate at

● Curb Box

Garage in Back of
34 Sheridan

