

LABOR AND MATERIALS

1	Copper } Connection ^{3/4}	\$
1	Lead } Cock Valve } in.	\$
1	Curb } T.S. & V. }	\$
1	Service box { Short 2-1/2 x 4-1/2 } Old returned { Long 4-1/2 x 5-1/2 }	\$
9	Ft. ^{3/4} in. { Copper } Pipe at	\$
	Nipples _____ in. at	\$
	Bushings _____ to _____ in. at	\$
	Red'g	
	Inc'g	
	Union _____ in. at	\$
	Meter _____ in. at	\$
	Compound Joints at	\$
	Maintenance Foreman	\$
	Hrs. Water Maint. Man - 1 at	\$
	Hrs. Water Maint. Man - 2 at	\$
	Hrs. Garage Foreman _____ at	\$
	Hrs. Labor _____ at	\$
	Hrs. Compressor at	\$
	Trucking	\$
	Pav't Patch	\$
		\$
		\$
		\$
		\$
		\$
		\$

St. GARFIELD No. 58-60
 Name of Owner _____

Labor and Mat'l. Report 1934, MAY 12



42'-10" 46'-2"

● Curb Box

CUNNINGHAM AVE.

6" Main

Elev. of Main at tap 45'

Gate at ●

● Gate at

● Curb Box