

LABOR AND MATERIALS

1	Copper	Connection		\$
1	Curb	Cock Valve Tr.C. & V.	in.	\$
1	Service box	Short 3-1/2 x 4-1/2		\$
	Old returned	Long 4-1/2 x 5-1/2		\$
21	Ft. 3/4 in.	Copper Pipe	at	\$
	Nipples	in.	at	\$
1	Bushings	3/4 to 1/2	in. at	\$
	Red'g			\$
	Inc'g			\$
	Union	in.	at	\$
	Meter	in.	at	\$
	Compound Joints	at		\$
	Maintenance Foreman			\$
	Hrs. Water Maint. Man - 1	at		\$
	Hrs. Water Maint. Man - 2	at		\$
	Hrs. Garage Foreman	at		\$
	Hrs. Labor	at		\$
	Hrs. Compressor	at		\$
	Trucking			\$
	Pav't Patch			\$
				\$
				\$
				\$
				\$
				\$

St. GARFIELD Ave. No. 6

Name of Owner
TAX ID # 302.19-21-3

Labor and Mat'l. Report 1931, APR. 22



26-9 20-8

● Curb Box

6" Main Elev. of Main at tap 5'

Gate at ● ● Gate at

● Curb Box