LABOR AND MATERIALS

	\$
Curb Cock Velve 10.	_ \$
Service box Short 3-1/2 x 4-1/2 Old returned Long 4-1/2 x 5-1/2	_ \$
$\frac{34}{2}$ Ft. $\frac{34}{4}$ in. $\left\{\begin{array}{c} \text{Copper} \\ \text{GI.} \end{array}\right\}$ Pipe at	
Nipples in. at	
Bushings to in. at	_ \$
Red'g	
Inc'g	
Union in. at	_ \$
Meter in. at	\$
	_ \$
Compound Joints at	\$
Maintenance Foreman	\$
Hrs. Water Maint, Man - 1 at	\$
Hrs. Water Maint. Man - 2 at	\$
Hrs. Garage Foreman at	\$
Hrs. Labor at	\$
Hrs. Compressor at	_ \$
	\$
Trucking	_ \$
Pav't Patch	
	\$
	\$
	\$
	\$

GEER	St. 45
Name of Owner	
TAX ID # 303.18-	8-7
Labor and Mat'l. Report	1926, OCT. 22
d	L
35	25 384"
	Curb Box
Main	Elev. of Main at tap
Gate at	• Gate at
	1
	Curb Box