

LABOR AND MATERIALS

3/4 } Copper } Connection _____ \$ _____
 Lead }
 _____ Curb } Cock } _____ in. _____ \$ _____
 Valve }
 T.S. & V. }
 _____ Service box { Short 3-1/2 x 4-1/2 } _____ \$ _____
 Old returned { Long 4-1/2 x 5-1/2 }
 22 Ft. _____ in. { Copper } Pipe at _____ \$ _____
 G.I.
 C.I.
 _____ Nipples _____ in. at _____ \$ _____
 _____ Bushings _____ to _____ in. at _____ \$ _____
 _____ Red'g _____
 _____ Inc'g _____
 _____ Union _____ in. at _____ \$ _____
 _____ Meter _____ in. at _____ \$ _____
 _____ \$ _____
 _____ Compound Joints at _____ \$ _____
 _____ Maintenance Foreman _____ \$ _____
 _____ Hrs. Water Maint. Man - 1 at _____ \$ _____
 _____ Hrs. Water Maint. Man - 2 at _____ \$ _____
 _____ Hrs. Garage Foreman _____ at _____ \$ _____
 _____ Hrs. Labor _____ at _____ \$ _____
 _____ Hrs. Compressor at _____ \$ _____
 _____ \$ _____
 _____ Trucking _____ \$ _____
 _____ Pav't Patch _____ \$ _____
 _____ \$ _____
 _____ \$ _____
 _____ \$ _____
 _____ \$ _____
 _____ \$ _____

ARBOR

St. 30-34
Pl.
Ave. No.

Name of Owner

Labor and Mat'l. Report 11/29/07

● Curb Box

6" Main

Elev. of Main at tap 6'

Gate at ●

● Gate at

● Curb Box

SEWER 10' 6" FROM CURB BOX 8" MAIN