

LABOR AND MATERIALS

1	Copper Lead Connection	3/4"	\$ 2.76
1	Curb Valve (T. S. & V.)	3/4 in.	\$ 3.49
1	Service box Old returned	Short 3 1/2 X 4 1/2 } Long 4 1/2 X 5 1/2 } Buffer Rdway }	\$ 4.74
27	Ft. 3/4 in. Copper G.I. Pipe at	35	\$ 9.45
	Nipples	in. at	\$
	Bushings	to in. at	\$
	Red'g Inc'g Coupl'gs	to in. at	\$
	Union	in. at	\$
	Meter	in. at	\$
	Lead Joints	at	\$
	Compound Joints	at	\$
	Hrs. Water Maint. Man-1	at	\$
2	Hrs. Water Maint. Man-2	at 1.24	\$ 2.48
10	Hrs. Labor	at 1.13	\$ 11.30
	Hrs. Labor	at	\$
	Hrs. Compressor	at	\$
	Compensation Ins.	at 3.706 per C	\$ 51
	Trucking		\$ 1.00
	Pay't Patch		\$ 7.09
	Tap by G. F. Ford	11-7-52	\$
	O'head		\$
			\$ 43.82

#44 Tax ID#302.11-6-32

#46 Tax ID# 302.11-6-33

~~St~~
~~Pt~~
 Ave. No. 44-46

Arbor Dr.

Name of Owner JOHNSON

Labor and Mat'l. Report Nov. 7 19 52

6" Main

Gate at ●

Elev. of Main at tap 5'

● Gate at

● Curb Box

LSM-5C 5 15-48