LABOR AND MATERIALS

1 Copper / ~~Lead~~ } Connection 3/4" $

1 Curb { Cock / ~~Valve~~ / ~~T. S. & V.~~ } 3/4 in. $

1 Service box { Short 3½ x 4½ / ~~Long 4½ x 5½~~ / ~~Buff or Fdway~~ } $

~~Old returned~~

11 Ft. 3/4 in. { Copper / ~~G. I.~~ / ~~C. I.~~ } Pipe at $

Nipples ____ in. at ____ $

Bushings ____ to ____ in. at ____ $

Red'g / Inc'g } Coupl'gs ____ to ____ in. at ____ $

Union ____ in. at ____ $

Meter ____ in. at ____ $

Lead Joints at ____ $

Compound Joints at ____ $

Maintenance Foreman ____ $

Hrs. Water Maint. Man—1 at ____ $

Hrs. Water Maint. Man—2 at ____ $

Hrs. Garage Foreman ____ at ____ $

Hrs. Labor— ____ at ____ $

Hrs. Compressor at ____ $

Compensation Ins. at $ ____ per C ____ $

Trucking ____ $

Pav't Patch ____ $

Tap by Gissoid & Co $

11-1-57 $

$

O'head ____ $

$

V

Ashley St. / Pl. / Ave. No. 5 / 7

Name of Owner

Dr. Wm. Simmonds

Labor and Mat'l. Report Nov. 1 19 57

● Curb Box

12" Main

Elev. of Main at tap 5'

Gate at ●

● Gate at

● Curb Box

LSM—5C—2-5 56