

### LABOR AND MATERIALS

1	Copper Lead	} Connection	1" in.	\$ 2.79	
1	Curb	{ Cock Valve T. S. & V. }	1" in.	\$ 3.60	
	Service Box Old returned	{ Short 3 1/2 x 4 1/2 Long 4 1/2 x 5 1/2 Buffer Rdway }		\$	
25	Ft. 7" in.	{ Copper Galv. Iron Cast Iron }	Pipe at 23	\$ 5.75	
	Nipples	..... in. at		\$	
	Bushings	..... to .....	in. at	\$	
1	Red'g Inc'g	} Couplings	1" to Brass	\$	
1	Union	1 1/2 in. at	Brushon Brass	\$	
1	Meter	1 1/2 in. at	Brass Nipple	\$	
1	Lead Joints	at 1" Coupling	4 1/2 in	\$	
	Leadite Joints	at fitters		\$	
	Hrs. Foreman	at		\$	
49	Hrs. Chauffeur	at 68.34		\$ 33.69	
	Hrs. Tapper	at		\$	
22	Hrs. Labor	at 62.2		\$ 13.75	
6	Hrs. Labor	at		\$ 3.60	
	Hrs. Compressor	at		\$	
	Compensation Ins.			\$ 1.36	
	Trucking			\$	
	Builders Use of Water			\$	
				\$	
				\$	
				\$	
				\$	
				\$	

3945

Basin

St. \_\_\_\_\_  
Pl. \_\_\_\_\_  
Ave. No. \_\_\_\_\_

Name of Owner  
Finch & Pruyn

Labor and Mat'l. Report April 3 19 45

Basin at 70.8'      83'10"      Basin at

● Curb Box  
Manhole

6" Main Elev. of Main at top 7.3

Gate at ● ● Gate at

● Curb Box

Basin at