

LABOR AND MATERIALS

1	Copper Lead	Connection	$\frac{3}{4}$	\$	_____
1	Curb	Cock Valve T.S. & V.	$\frac{3}{4}$ in.	\$	_____
	Service box Old returned	{ Short $3\frac{1}{2} \times 4\frac{1}{2}$ Long $4\frac{1}{2} \times 5\frac{1}{2}$ Buff or Rdway		\$	_____
34	Ft.	$\frac{3}{4}$ in.	{ Copper G.I. G.I.	Pipe at	\$ _____
	Nipples	in. at		\$	_____
	Bushings	to in. at		\$	_____
	Red'g Inc'g	Coupl'gs	to in. at	\$	_____
	Union	in. at		\$	_____
	Meter	in. at		\$	_____
	Lead Joints	at		\$	_____
	Compound Joints	at		\$	_____
	Maintenance Foreman			\$	_____
	Hrs. Water Maint. Man	—1 at		\$	_____
	Hrs. Water Maint. Man	—2 at		\$	_____
	Hrs. Garage Foreman	at		\$	_____
	Hrs. Labor	at		\$	_____
	Hrs. Compressor	at		\$	_____
	Compensation Ins.	at \$ _____ per C		\$	_____
	Trucking			\$	_____
	Pav't Patch			\$	_____
	O'head			\$	_____
				\$	_____

BAY St. Ave. No. 106
 Name of Owner
 TAX ID # 302.16-19-3

