

Labor and Materials

1	Lead Connection <i>3/4</i>	\$
2	Curb Cock <i>1 1/2"</i>	\$
1	Service Box (Short $3\frac{1}{2}$ x $4\frac{1}{2}$ Old returned Long $4\frac{1}{2}$ x $5\frac{1}{2}$ Buffalo)	\$
8	Ft. <i>1"</i> in. G. I. Pipe at	\$
	Nipples in. at	\$
	Bushings to in. at	\$
	Red'g Coup to in. at	\$
	Inc'g Coup to in. at	\$
	Union in. at	\$
	Meter in. at	\$
	Cu. Yds. Br. Stone at	\$
	Cu. Yds. Sand at	\$
	Bags Cement at	\$
	Paving Brick { Mack Red Asphalt } at	\$
4	Hrs. Foreman at	\$
8	Hrs. Common Labor at	\$
	Hrs. Mason at	\$
	Hrs. at	\$
	Hrs. at	\$
<i>900</i>	Builders' Use of Water	\$
<i>Trucks 100</i> at	\$
 at	\$
 at	\$
 at	\$
	Total \$	<i>18.95</i>

WEST BERTON

Labor and Material Report *1924*

3/4 Tap for Wood Pipe

● Curb Box

11" Pipe from Main to

Main Elev. of Main at tap *4*

Gate at ● Gate at

● Curb Box