

Labor and Materials

Copper	Connection	3 4		\$ 1.23
Lead				
Curb	Cock Valve T. S. & V.	3/4	in	\$ 1.68
Service Box	Short 3/4 x 4 1/2 Long 4 1/2 x 5 1/2 Buff. or Rdway			\$ 1.75
Old returned				
9 Ft. 3/4 in.		Copper Cast-iron	15	Pipe at
Nipples	in. at			\$
Bushings	to in. at			\$
Red'g Inc'g	Couplings		to in. at	\$
Union	in. at			\$
Meter	in. at			\$
Lead Joints	at			\$
Leadite Joints	at			\$
Hrs. Foreman	at			\$ 4.37
7 Hrs. Chauffeur	at 6 1/2 hr			\$
Hrs. Tapper	at			\$ 7.65
17 Hrs. Labor	at 4.5			\$
Hrs. Labor	at			\$.88
1 Hrs. Compressor	at			\$ 37
Compensation Ins.				\$ 1.00
Trucking				\$ 5.00
Builders Use of Water	Patch -			\$
Tape by P.M.C.I.				\$
				\$
				\$
				\$
				\$ 25.28

74-1938

13

St. _____
Pl. _____
Ave. No. 12

Birch

Name of Owner _____

Labor and Mat'l. Report July 30, 1938



● Curb Box

4" Main

Elev. of Main at tap 6 1/2

● Gate at

● Gate at

TAX ID # 302.16-18-15

● Curb Box

Old tap dug up.

Take Paid for. *[initials]*