

LABOR AND MATERIALS

1	Copper	} Connection $\frac{3}{4}$ "	\$ 3.08
	Lead		
1	Curb	} $\frac{3}{4}$ in.	\$ 3.89
	Cock		
	Valve T.S. & V.		
1	Service box	} { Short $3\frac{1}{2}$ x $4\frac{1}{2}$ Long $4\frac{1}{2}$ x $5\frac{1}{2}$ Buff or Rdway	\$ 4.32
	Old returned		
24	Ft. $\frac{3}{4}$ in.	} Pipe at 45	\$ 10.80
	Nipples	in. at	\$
	Bushings	to in. at	\$
	Red'g	} Coupl'gs	to in. at \$
	Inc'g		
	Union	in. at	\$
	Meter	in. at	\$
	Lead Joints	at	\$
	Compound Joints	at	\$
3	Maintenance Foreman	1.937	\$ 5.81
	Hrs. Water Maint. Man-1	at	\$
4	Hrs. Water Maint. Man-2	at 1.613	\$ 6.45
2	Hrs. Garage Foreman	lab. at 1.491	\$ 2.96
16	Hrs. Labor	at 1.30	\$ 20.80
	Hrs. Compressor	at	\$
	Compensation Ins. at \$ 5.686	per C	\$ 2.05
	Trucking		\$ 1.50
	Pav't Patch	Before Paving	\$
	Tap by Gifford & Co		\$
		6-20-56	\$
	O'head		\$
			\$
			\$ 61.66

Birch -St. -
-Pl. -
Ave. No. 23

Name of Owner
W. Edward Kingsley

Labor and Mat'l. Report June 20 1956

4" Main Elev. of
Main at tap 5 1/2'

Gate at • • Gate at

TAX ID # 302.20-6-10

• Curb Box

Before Paving.