

Labor and Materials

1. Lead } Copper Connection. $\frac{3}{4}$	\$ 1.33
1. Curb } Cock Valve } $\frac{3}{4}$ in	\$ 1.58
1. Service Box } Short $3\frac{1}{2} \times 4\frac{1}{2}$	\$ 1.36
Old returned } Long $4\frac{1}{2} \times 5\frac{1}{2}$	
21. Ft. $\frac{3}{4}$ in. } Copper Galv. Iron } Pipe at	\$ 2.10
Nipples	in. at \$
Bushings	to in. at \$
Red'g Inc'g } Couplings	to in. at \$
Union	in. at \$
Meter	in. at \$
Lbs. Br. Stone	at \$
Lbs. Sand	at \$
Bags Cement	at \$
Paving Brick } Mack Red Asphalt }	at \$
Lead Joints	at \$
Leadite Joints	at \$
3 Hrs. Foreman	at \$ 1.88
8 Hrs. Common Labor	at \$ 4.00 <i>Tapper</i>
9 Hrs. Common Labor	at \$ 3.60
Hrs. Mason	at \$
Hrs. Masons Helper	at \$
Hrs. Compressor	at \$
Compensation Ins	at \$ 1.29
Trucking	at \$
Builders Use of Water	at \$ 5.00 <i>Patch</i>
Total \$ 22.14	

33-12 #15

Labor and Material Report *Apr. 18* 1933

11 Birch Ave.

4" Main Elev. of Main at tap *6"*

Gate at ● ● Gate at

● Curb Box

TAX ID # 302.20-6-14

old tap disconnected at main

OK *M*