

LABOR AND MATERIALS

1	Copper Lead	} Connection $3/4"$	\$
1	Curb		} Cock Valve T.S. & V. $3/4"$ in.
1	Service box Old returned	} Short $3\frac{1}{2} \times 4\frac{1}{2}$ Long $4\frac{1}{2} \times 5\frac{1}{2}$	
24	Ft. $3/4"$ in.		} {Copper C.I. C.I. } Pipe at
	Nipples	in. at	
	Bushings	to in. at	\$
	Red'g Inc'g	} Coupl'gs. to in. at	\$
	Union		in. at
	Meter	in. at	\$
	Compound Joints	at	\$
	Maintenance Foreman		\$
	Hrs. Water Maint. Man-1	at	\$
	Hrs. Water Maint. Man-2	at	\$
	Hrs. Garage Foreman	at	\$
	Hrs. Labor	at	\$
	Hrs. Compressor	at	\$
	Trucking		\$
	Pav't Patch		\$
			\$
			\$
			\$
			\$
			\$

BOWMAN Ave. No. 7

Name of Owner

Labor and Mat'l. Report MAY 1935



● Curb Box

6" Main Elev. of Main at tap $4\frac{1}{2}'$

Gate at ● Gate at

● Curb Box

OLD TAP SHUT OFF AT MAIN

OLD TAP SHUT OFF AT MAIN