

Labor and Materials

1.. Lead Connection ^{1/2}	\$
1.. Curb Cock ^{3/4}	\$
1.. Service Box { Short 3 1/2 x 4 1/2 Old returned { Long 4 1/2 x 5 1/2 Buffalo	\$
8.. Ft. ^{3/4} in. G. I. Pipe at	\$
Nipples..... in. at	\$
Bushings..... in. at	\$
Red'g Coup... to... in. at	\$
Inc'g Coup... to... in. at	\$
Union... in. at	\$
Meter... in. at	\$
Cu. Yds. Br. Stone at	\$
Cu. Yds. Sand at	\$
Bags Cement at	\$
Pav. Brick { Mack { Red { Asphalt } at	\$
1.. Hrs. Foreman at	\$
1.. Hrs. Com. Labor at	\$
Hrs. Mason at	\$
Hrs. at	\$
Hrs. at	\$
Builders' Use of Water	\$
..... at	\$
..... at	\$
..... at	\$
..... at	\$
Total \$ <u>8.67</u>	

Labor and Material Report

June 14 1921

1/2" Tap on Boylston St

● Curb Box

6

Main

Elev. of
Main at tap 4 1/2

Gate at ●

● Gate at

● Curb Box