

# LABOR AND MATERIALS

_____	Copper } Connection _____	\$ _____
_____	Lead } _____	\$ _____
_____	<sup>GATE</sup> Curb } <sup>Seek</sup> Valve } _____ in.	\$ _____
_____	<sup>GATE</sup> Service box { Short 3-1/2 x 4-1/2 } _____	\$ _____
_____	Old returned { Long 4-1/2 x 5-1/2 } _____	\$ _____
_____	Ft. <u>6</u> in. { <sup>Copper</sup> C.I. } Pipe at _____	\$ _____
_____	Nipples _____ in. at _____	\$ _____
_____	Bushings _____ to _____ in. at _____	\$ _____
_____	Red'g _____	\$ _____
_____	Inc'g _____	\$ _____
_____	Union _____ in. at _____	\$ _____
_____	Meter _____ in. at _____	\$ _____
_____	_____	\$ _____
_____	Compound Joints at _____	\$ _____
_____	Maintenance Foreman _____	\$ _____
_____	Hrs. Water Maint. Man - 1 at _____	\$ _____
_____	Hrs. Water Maint. Man - 2 at _____	\$ _____
_____	Hrs. Garage Foreman _____ at _____	\$ _____
_____	Hrs. Labor _____ at _____	\$ _____
_____	Hrs. Compressor at _____	\$ _____
_____	_____	\$ _____
_____	Trucking _____	\$ _____
_____	Pav't Patch _____	\$ _____
_____	_____	\$ _____
_____	_____	\$ _____
_____	_____	\$ _____
_____	_____	\$ _____

3 BROAD ST. PLAZA  
BROAD

St. PLAZA  
 Pl. \_\_\_\_\_  
 Ave. No. 3

Name of Owner  
RENAL CENTER

Labor and Mat'l. Report 19 SEPT. 2000

#57  
 MONTCALM

38'2"      30'11"

● Curb Box  
 GATE

6" Main

Elev. of Main at tap \_\_\_\_\_

Gate at ●      ● Gate at

● Curb Box

TAP ON MONTCALM ST.

LABOR AND MATERIALS

Copper	} Connection <sup>3/4</sup>	\$	
Lead			
Curb	} Cock Valve } <sup>3/4</sup> in.	\$	
		T.S. & V.	
Service box	} Short 3 1/2 x 4 1/2 }		
Old returned		Long 4 1/2 x 5 1/2 }	\$
28 Ft.	} <sup>3/4</sup> in. { Copper } Pipe at	\$	
		{ C.T. }	
Nipples	in. at	\$	
Bushings	to in. at	\$	
Red'g	} Coupl'gs to in. at	\$	
Inc'g			
Union	in. at	\$	
Meter	in. at	\$	
		\$	
Compound Joints	at	\$	
Maintenance Foreman		\$	
Hrs. Water Maint. Man	-1 at	\$	
Hrs. Water Maint. Man	-2 at	\$	
Hrs. Garage Foreman	at	\$	
Hrs. Labor	at	\$	
Hrs. Compressor	at	\$	
		\$	
Trucking		\$	
Pav't Patch		\$	
		\$	
		\$	
		\$	
		\$	

BROAD

St. ~~Pl.~~  
Ave. No. 12537

Name of Owner

Labor and Mat'l. Report AUG 1934



● Curb Box

6" Main

Elev. of Main at tap 5'

Gate at ●

FIELDING ST

● Gate at

● Curb Box