

LABOR AND MATERIALS

1	Copper Lead	Connection	3/4	\$	1.35
1	Curb	Cock Valve F.S. & V.	3/4 in.	\$	1.80
1	Service Box Old returned	Short 3"x4 1/2" Long 4"x5 1/2" Buffer Rdway		\$	1.70
38	Ft. of	Copper Galv Iron Cast Iron	Pipe at 1.8	\$	6.84
	Nipples	in. at		\$	
	Bushings	to in. at		\$	
	Red'g Inc'g	Couplings to in. at		\$	
	Union	in. at		\$	
	Meter	in. at		\$	
	Lead Joints	at		\$	
	Leadite Joints	at		\$	
	Hrs. Foreman	at		\$	
4	Hrs. Chauffeur	at	6.2 hr	\$	2.50
9	Hrs. Tapper	at	4	\$	5.62
14	Hrs. Labor	at	4.5	\$	6.30
	Hrs. Labor	at		\$	
5	Hrs. Compressor	at	1.62 hr	\$	3.13
	Compensation Ins.			\$.44
	Trucking			\$	1.50
	Builders Use of Water	Patch		\$	5.00
				\$	
				\$	
				\$	
				\$	
				\$	
				\$	35.68

2 1941

~~192~~
Broad

St. PL Ave. No. 158

Name of Owner

Suckman

Labor and Mat'l. Report

April 16 1941



6 Main

Elev. of Main at tap 4 1/2

Gate at ●

● Gate at

● Curb Box

Measured in from
 190 Broad St.

~~192 Broad St to street name~~