

LABOR AND MATERIALS

1	Copper	}	Connection	<u>3/4"</u>		\$	
	Lead						
1	Curb	}	Cock Valve T.S. & V.	<u>3/4"</u>		\$	
				in.			
	Service box	}	Short $3\frac{1}{2} \times 4\frac{1}{2}$				
	Old returned		Long $4\frac{1}{2} \times 5\frac{1}{2}$				
			Buff or Rdway			\$	
10	Ft.	}	Copper				
	<u>3/4"</u>		G.I.	} Pipe at			
	in.		G.I.				\$
	Nipples		in.	at		\$	
	Bushings		to	in.	at	\$	
	Red'g	}	Coupl'gs	to	in.	at	
	Inc'g						\$
	Union		in.	at		\$	
	Meter		in.	at		\$	
	Lead Joints		at			\$	
	Compound Joints		at			\$	
	Maintenance Foreman					\$	
	Hrs. Water Maint. Man		1	at		\$	
	Hrs. Water Maint. Man		2	at		\$	
	Hrs. Garage Foreman			at		\$	
	Hrs. Labor			at		\$	
	Hrs. Compressor			at		\$	
	Compensation Ins.		at \$		per C	\$	
	Trucking					\$	
	Pav't Patch					\$	
						\$	
						\$	
						\$	
	O'head					\$	
						\$	

St.
Pt.
Ave. No. 193

193 BROAD

Name of Owner

GINSBURG

Labor and Mat'l. Report

measured
OCT

1981



LUZERNE RD.

4 Main

Elev. of
Main at tap 4 1/2'

Gate at ●

● Gate at

● Curb Box

*Believe the building was
changed - new trees for
old tap*