

LABOR AND MATERIALS

Copper	} Connection	-----	\$
Lead		-----	\$
Curb	} Cock Valve T. S. & V.	-----	in. \$
Service Box		-----	\$
Old returned	} Short 3/2x4 1/2 Long 4 1/2x5 1/2 Buff. or Rdway	-----	\$
Ft. -----		-----	\$
in. -----		-----	\$
	} Copper Galv Iron Cast Iron	-----	Pipe at \$
Nipples		-----	in. at \$
Bushings		-----	to ----- in. at \$
Red'g	} Couplings	-----	to ----- in. at \$
Inc'g		-----	\$
Union	-----	in. at \$	
Meter	-----	in. at \$	
Lead Joints	-----	at \$	
Leadite Joints	-----	at \$	
Hrs. Foreman	-----	at \$	
Hrs. Chauffeur	-----	at \$	
Hrs. Tapper	-----	at \$	
Hrs. Labor	-----	at \$	
Hrs. Labor	-----	at \$	
Hrs. Compressor	-----	at \$	
Compensation Ins.	-----	\$	
Trucking	-----	\$	
Builders Use of Water	-----	\$	
	-----	\$	
	-----	\$	
	-----	\$	
	-----	\$	

St. *25-30*

Pt. *Broad* Ave. No. *16*

Name of Owner _____

Labor and Mat'l. Report *Dec. 8,* 19*26*



Broad St.

8" Main *New Pruyn St.* Elev. of Main at top *4'*

Gate at ● ● Gate at

TAX ID # 309.28-9-5

● Curb Box

*See card for
16 New Pruyn St.*