

LABOR AND MATERIALS

1	Copper Lead	Connection	3/4 1 1/2	\$ 280
1	Curb	Clock Valve T. S. & V.	2 1/2 in.	\$ 360
1	Service box	Short 3 1/2 X 4 1/2 Long 4 1/2 X 5 1/2 Buffer Rdway		\$ 590
	Old returned			
40	Ft	1 1/2 in.	Copper Galv. Iron Cast Iron	Pipe at \$
	Nipples	in. at		\$
	Bushings	to in. at		\$
	Red'g Inc'g	Couplings	to in. at	\$
	Union	in. at		\$
	Meter	in. at		\$
	Lead Joints	at		\$
	Compound Joints	at		\$
	Hrs. Foreman	at		\$
17	Hrs. Chauffeur	at	8 2 1/2	\$ 990
4	Hrs. Tapper	at	8 2 1/2	\$ 330
33	Hrs. Labor	at	7 1/2	\$ 2360
	Hrs. Labor	at		\$
2	Hrs. Compressor	at	8 7 1/2	\$ 175
	Compensation Ins.			\$ 81
	Trucking			\$ 150
	Builders Use of Water			\$ 17.50
	Tap by Worsinslas			\$
				\$
				\$
				\$
				\$
				\$

33-47

St. Pt. Ave. No. 1016

Broad

Name of Owner Atlantic Oil Co.
Warren County Bldg.

Labor and Mat'l. Report June 3 1947

RAZED - 1993

Gate at ● Broad St. ● Gate at

● Curb Box

This Tap on Broad St.
Re-measured
Feb. 16, 1967