

LABOR AND MATERIALS

1/ Copper } Connection $1\frac{1}{2}$ \$ 1.78
 Lead }
 1/ Curb } Clock } $\frac{3}{4}$ in. \$ 2.61
 Valve } T.S. & V. }
 1/ Service box } Short $3\frac{1}{2} \times 4\frac{1}{2}$
 Old returned } Long $4\frac{1}{2} \times 5\frac{1}{2}$
 Buff or Rdway } \$ 1.82
 9 Ft. $\frac{3}{4}$ in. } Copper } Pipe at 23 \$ 207
 Galv. Iron }
 Cast Iron }
 Nipples in. at \$
 Bushings to in. at \$
 Red'g } Couplings to in. at \$
 Inc'g }
 Union in. at \$
 Meter in. at \$
 Lead Joints at \$
 Compound Joints at \$
 Hrs. Foreman at \$
 Hrs. Chauffeur at \$
 8 Hrs. Tapper at 75 \$ 6.00
 6 Hrs. Labor at 65 \$ 3.90
 Hrs. Labor at \$
 Hrs. Compressor at \$
 Compensation Ins. 27 \$
 Trucking 1.00 \$
 Builders Use of Water Patch? 5.00 \$
 Tap by McGowan \$
 \$ 24.45

26-45

St. *LSH B*
 -Pl-
 Ave. No. *45*
 Broad

Name of Owner
Jos Fish

Labor and Mat'l Report *May 14* 1946

2" Main Elev. of Main at tap 7
 Gate at ● Gate at ●

Old tap to be dug up on Broadway
 Dug up + shipped off at ● Curb Box
 Main

TAX ID #309.27-6-6

LSM-5C-6-1-45 *this tap on North Delaware L*