

### Labor and Materials

1	Lead Connection	\$	.....	\$
1	Curb Cock	\$	.....	\$
1	Service Box (Short 3" x 4") Old returned Buffalo	\$	.....	\$
37	Ft. in. G. I. Pipe at	\$	.....	\$
	Nipples in. at	\$	.....	\$
	Bushings to in. at	\$	.....	\$
	Red'g Coup to in. at	\$	.....	\$
	Inc'g Coup to in. at	\$	.....	\$
	Union in. at	\$	.....	\$
	Meter in. at	\$	.....	\$
	Cu. Yds. Br. Stone at	\$	.....	\$
	Cu. Yds. Sand at	\$	.....	\$
	Bags Cement at	\$	.....	\$
	Paving Brick { Mack Red Asphalt } at	\$	.....	\$
2	Hrs. Foreman at	\$	.....	\$
4	Hrs. Common Labor at	\$	.....	\$
	Hrs. Mason at	\$	.....	\$
	Hrs. at	\$	.....	\$
	Hrs. at	\$	.....	\$
Pro	Builders' Use of Water	\$	.....	\$
	<i>7.116.6.1.2.2</i> at	\$	.....	\$
	at	\$	.....	\$
	at	\$	.....	\$
	at	\$	.....	\$
	Total	\$	.....	\$

### Labor and Material Report

June 16 196

50 Broad St.

6 Main      Elev. of Main at tap 5

Gate at •      • Gate at

Urban Renewal

● Curb Box

Shut off at Curb  
MAY-22-1974