

LABOR AND MATERIALS

1	Copper	} Connection	3/4"	}	\$			
	Lead							
1	Curb	} Cock } Valve } T-S. & V.	} 3/4" in.	}	\$			
1	Service box					} Short 3 1/2 x 4 1/2	}	\$
	Old returned							
9	Ft.	} Copper } C.I. } C.I.	} 3/4 in.	} Pipe at	\$			
	Nipples					in. at	\$	
	Bushings					to in. at	\$	
	Red'g Inc'g	} Coupl'gs	to in. at	\$				
	Union				in. at	\$		
	Meter	in. at	\$					
	Compound Joints	at	\$					
	Maintenance Foreman		\$					
	Hrs. Water Maint. Man	1 at	\$					
	Hrs. Water Maint. Man	2 at	\$					
	Hrs. Garage Foreman	at	\$					
	Hrs. Labor	at	\$					
	Hrs. Compressor	at	\$					
	Trucking		\$					
	Pav't Patch		\$					
			\$					
			\$					
			\$					
			\$					
			\$					

BROAD

St. REAR
Pl.
Ave. No. 73

Name of Owner

Labor and Mat'l. Report

MAY 1934



51 1/2" 39 1/2"

● Curb Box

6" Main

Elev. of Main at tap 5'

Gate at ●

● Gate at

● Curb Box