

Labor and Materials

1. Copper } Connection $\frac{3}{4}$ in.	\$ 3.20
1. Curb } Cock Valve } $\frac{3}{4}$ in.	\$ 1.00
X. Service Box } Short $3\frac{1}{2} \times 4\frac{1}{2}$	Old curb put back
Old returned } Long $4\frac{1}{2} \times 5\frac{1}{2}$	
39 Ft. $\frac{3}{4}$ in. } Copper } Pipe at	\$ 8.58
	Cast Iron
Nipples..... in. at.....	\$
Bushings..... to..... in. at.....	\$
1 Red'g } Couplings $\frac{3}{4}$ in. at	\$ 1.5
1 In'g } to Brass	
Union..... in. at.....	\$
Meter..... in. at.....	\$
Lbs. Br. Stone at.....	\$
Lbs. Sand at.....	\$
Bags Cement at.....	\$
Paving Brick } Mack } at	\$
	Red
	Asphalt
Lead Joints at.....	\$
Leadite Joints at.....	\$
7 Hrs. Foreman at... 6.25	\$ 2.50
2.4 Hrs. Common Labor at... 5.0	\$ 2.00
Hrs. Common Labor at.....	\$
Hrs. Mason at.....	\$
Hrs. Mason's Helper at.....	\$
Hrs. Compressor at.....	\$
Compensation Ins.....	\$.38
Trucking.....	\$ 1.00
Builders' Use of Water.....	\$
Total \$ 28.21	
Old Curb not used	

Labor and Material Report

July 25

1926

52 Broadway St

#74



6" Main

Elev. of Main at top 5'

Gate at ●

● Gate at

● Curb Box

Old curb not
put back

Shut off at curb
3-6-1925