

Labor and Materials

| | | | |
|-----------|--|--|-----------|
| 1 | Copper } Connection <i>3/4"</i> | | \$ 3.20 |
| 1 | Lead } Lead | | |
| 1 | Curb { Cock } <i>3/4"</i> in. | | \$ 1.00 |
| | { Valve } | | |
| | { T.S. & V. } | | |
| 1 | Service Box { Short 3 1/2 x 4 1/2 } | | \$ 1.30 |
| | Old returned { Long 4 1/2 x 5 1/2 } | | |
| | { Buff. or Railway } | | |
| <i>35</i> | Ft. <i>3/4"</i> in. { Copper } Pipe at. | | \$ 7.70 |
| | { Galv. Iron } | | |
| | { Cast Iron } | | |
| | Nipples..... in. at..... | | \$ |
| | Bushings..... to..... in. at..... | | \$ |
| 1 | Red g } Couplings. <i>Broad</i> to..... in. at..... | | \$ 1.5 |
| | Lead } Lead | | |
| | Union..... in. at..... | | \$ |
| | Meter..... in. at..... | | \$ |
| | Lbs. Br. Stone at..... | | \$ |
| | Lbs. Sand at..... | | \$ |
| | Bags Cement at..... | | \$ |
| | Paving Brick { Mack } at..... | | \$ |
| | { Red } | | |
| | { Asphalt } | | |
| | Lead Joints at..... | | \$ |
| | Leadite Joints at..... | | \$ |
| 7 | Hrs. Foreman at..... <i>6.2.5</i> | | \$ 4.37 |
| 20 | Hrs. Common Labor at..... <i>50</i> | | \$ 10.00 |
| 18 | Hrs. Common Labor at..... <i>3.25</i> | | \$ 7.31 |
| | Hrs. Mason at..... | | \$ |
| | Hrs. Mason's Helper at..... | | \$ |
| | Hrs. Compressor at..... | | \$ |
| | Compensation Ins..... | | \$ 1.57 |
| | Trucking..... | | \$ 1.00 |
| | Builders' Use of Water..... | | \$ |
| Total | | | \$ 36.60. |

26-104 "15"
Labor and Material Report

Aug 6

19 *76*

3/4" Tap at 56 Broad st



1" Main

Elev. of Main at tap *5.26*

Gate at ●

● Gate at

● Curb Box

Shut off at Curb

MARCH-25-1975