

LABOR AND MATERIALS

Copper } Connection _____	\$ _____
Lead } _____	
Curb } Cock _____	in. \$ _____
} Valve _____	
} T. S. & V. _____	
Service box } Short 3½ x 4½ } _____	
Old returned } Long 4½ x 5½ } _____	\$ _____
Ft. 2 in. } Copper } Pipe at _____	\$ _____
} C.I. } _____	
} C.I. } _____	
Nipples _____ in. at _____	\$ _____
Bushings _____ to _____ in. at _____	\$ _____
Red'g } _____	
Inc'g } Coupl'gs _____ to _____ in. at _____	\$ _____
Union _____ in. at _____	\$ _____
Meter _____ in. at _____	\$ _____
_____	\$ _____
Compound Joints at _____	\$ _____
Maintenance Foreman _____	\$ _____
Hrs. Water Maint. Man—1 at _____	\$ _____
Hrs. Water Maint. Man—2 at _____	\$ _____
Hrs. Garage Foreman _____ at _____	\$ _____
Hrs. Labor— _____ at _____	\$ _____
Hrs. Compressor at _____	\$ _____
_____	\$ _____
Trucking _____	\$ _____
Pav't Patch _____	\$ _____
_____	\$ _____
_____	\$ _____
_____	\$ _____
_____	\$ _____

**BROAD**

St. \_\_\_\_\_  
~~Pt.~~ \_\_\_\_\_  
 Ave. No. **84**

Name of Owner \_\_\_\_\_

---

Labor and Mat'l. Report 19 **90**

● Curb Box

GATE

Main _____	Elev. of Main at tap _____
Gate at ● _____	● Gate at _____

---

● Curb Box

TAX ID #309.35-3-4

LSM-5C-6-1-67

**Labor and Materials**

1	Copper } Connection $\frac{3}{4}$ "	\$ 3.20
1	Lead } Connection $\frac{3}{4}$ "	
1	Curb { Cock Valve } $\frac{3}{4}$ " in.	\$ 1.00
	{ T.S. & V. }	
1	Service Box { Short $3\frac{1}{2}$ x $4\frac{1}{2}$ }	\$ 1.30
	Old returned { Long $4\frac{1}{2}$ x $5\frac{1}{2}$ }	
	{ Buff. or Rdway }	
26	Ft. $\frac{3}{4}$ " in. { Copper Galv. Iron } Pipe at.	\$ 7.92
	{ Cast Iron }	
	Nipples..... in. at.....	\$
1	Bushings $\frac{3}{4}$ " to $\frac{1}{2}$ " in. at.....	\$ .08
1	Redd'g } Couplings $\frac{3}{4}$ " to $\frac{1}{2}$ " in. at.....	\$ .15
	Inc'g }	
	Union..... in. at.....	\$
	Meter..... in. at.....	\$
	Lbs. Br. Stone at.....	\$
	Lbs. Sand at.....	\$
	Bags Cement at.....	\$
	Paving Brick { Mack Red Asphalt } at.....	\$
	Lead Joints at.....	\$
	Leadite Joints at.....	\$
3	Hrs. Foreman at $62.5$	\$ 1.88
8	Hrs. Common Labor at $5.0$	\$ 4.00
2	Hrs. Common Labor at $4.08$	\$ .81
	Hrs. Mason at.....	\$
	Hrs. Mason's Helper at.....	\$
	Hrs. Compressor at.....	\$
	Compensation Ins.....	\$ .19
	Trucking.....	\$ 1.00
	Builders' Use of Water.....	\$

Total 21.53  
*Paint Patch* 3  
24.53

**Labor and Material Report**

1926

*34 ft. 62' Road at*

RAZED *62' Road at #84*



Curb Box

6" Main

Elev. of Main at tap  $111$

Gate at ●

● Gate at

● Curb Box

*Shut off at Curb*

*MAR. 19-1925*