

LABOR AND MATERIALS

Copper } Connection.....	\$.....
Lead }	\$.....
Curb } Clock Valve }	in. \$.....
} T. S. & V. }	in. \$.....
Service box } Short 3 1/4 X 4 1/2 }	\$.....
Old returned } Long 4 1/4 X 5 1/2 }	\$.....
} Buff or Rdway }	\$.....
Ft. in. } Copper } Pipe at	\$.....
} Galv. Iron }	\$.....
} Cast Iron }	\$.....
Nipples in. at	\$.....
Bushings to in. at	\$.....
Red'g } Couplings..... to in. at.....	\$.....
Inc'g }	\$.....
Union in. at	\$.....
Meter in. at	\$.....
Lead Joints at	\$.....
Compound Joints at	\$.....
Hrs. Foreman at	\$.....
Hrs. Chauffeur at	\$.....
Hrs. Tapper at	\$.....
Hrs. Labor at	\$.....
Hrs. Labor at	\$.....
Hrs. Compressor at	\$.....
Compensation Ins.	\$.....
Trucking	\$.....
Builders Use of Water	\$.....
Measure by <i>Maximilian Gec</i>	\$.....
.....	\$.....
.....	\$.....
.....	\$.....
.....	\$.....
.....	\$.....
.....	\$.....

#76
 St. Broad
 Pt. 76
 Ave. No. 76

RAZED

Name of Owner

Labor and Mat'l. Report Dec 11 1941

ONY Pole #18

#76
#96

Curb Box
1 - 2' EYED CURB

..... Main

Elev. of Main at tap.....

Gate at ●

● Gate at

● Curb Box

NY Pole