

LABOR AND MATERIALS

1	Copper Lead	} Connection ^{3/4"}	\$
1	Curb		} Cock Valve } ^{3/4"} in. \$
		T.S. & V.	
1	Service box Old returned	} Short 3 1/2 x 4 1/2 } Long 4 1/2 x 5 1/2 }	\$
15	Ft. ^{3/4"} in.		} Copper } C.I. } C.I. }
	Nipples	in. at \$	
	Bushings	to in. at \$	
	Red'g Inc'g	} Coupl'gs to in. at \$	
	Union		in. at \$
	Meter	in. at \$	
	Compound Joints	at \$	
	Maintenance Foreman	\$	
	Hrs. Water Maint. Man-1	at \$	
	Hrs. Water Maint. Man-2	at \$	
	Hrs. Garage Foreman	at \$	
	Hrs. Labor	at \$	
	Hrs. Compressor	at \$	
	Trucking	\$	
	Pav't Patch	\$	
		\$	
		\$	
		\$	
		\$	
		\$	
		\$	

BROAD

St. Pt. Ave. No. 97

Name of Owner
TAX ID # 309.35-1-3

Labor and Mat'l. Report AUG 1926



310" 39'0"
● Curb Box

6" Main

Elev. of Main at tap 5'

Gate at ●

● Gate at

● Curb Box