

**Labor and Materials**

1	Copper	Connection	3/4"	\$	3.20
1	Curb	Cock Valve	3/4" in.	\$	1.00
		T. S. & V.			
	Service Box	Short 3 1/2 x 4 1/2		\$	1.30
	Old returned	Long 4 1/2 x 5 1/2			
		Buff. or Rdway			
33	Ft.	3/4" in.	Copper Galv. Iron Cast Iron Pipe at	\$	7.26
	Nipples	in. at		\$	
1	Bushings	3/4" to 1 1/2" in. at		\$	.98
1	Redd Incg	Couplings	1 1/2" to 2" in. at	\$	.15
	Union	in. at		\$	
	Meter	in. at		\$	
	Lbs. Br. Stone	at		\$	
	Lbs. Sand	at		\$	
	Bags Cement	at		\$	
	Paving Brick	Mack Red Asphalt at		\$	
	Lead Joints	at		\$	
	Leadite Joints	at		\$	
11	Hrs. Foreman	at	62.15	\$	6.00
33	Hrs. Common Labor	at	50	\$	16.50
4	Hrs. Common Labor	at	40.52	\$	1.62
	Hrs. Mason	at		\$	
	Hrs. Mason's Helper	at		\$	
	Hrs. Compressor	at		\$	
	Compensation Ins.			\$	6.6
	Trucking			\$	10.0
	Builders' Use of Water			\$	
				Total	\$ 396.5

26-99 #100

Labor and Material Report Aug 8 19 26

3/4" tap at 80 Broadway

to be disconnected in main

80 Broadway

Shut off at curb #100

5/26/24

47 1/2" Curb Box

Main

Elev. of Main at tap 5 1/2

Gate at

14' Curb Box

STORM SEWER