

Labor and Materials

Copper	Connection	\$				
Lead		\$				
Curb	Cock Valve T. S. & V. in.	\$				
				Service Box	Short 3 1/2 x 4 1/2	}	\$
				Old returned	Long 4 1/2 x 5 1/2 Buff. or Rdway		
Ft.	in.	Copper Galv. Iron Cast Iron	Pipe at.....	\$			
					Nipples	in. at.....	\$
					Bushings	to..... in. at.....	\$
Red'g Inc'g	Couplings	to..... in. at.....	\$				
				Union	in. at.....	\$	
Meter	in. at.....	\$					
Lbs. Br. Stone	at.....	\$					
Lbs. Sand	at.....	\$					
Bags Cement	at.....	\$					
Paving Brick	Mack Red Asphalt	} at.....	\$				
				Lead Joints	at.....	\$	
				Leadite Joints	at.....	\$	
Hrs. Foreman	at.....	\$					
Hrs. Common Labor	at.....	\$					
Hrs. Common Labor	at.....	\$					
Hrs. Mason	at.....	\$					
Hrs. Mason's Helper	at.....	\$					
Hrs. Compressor	at.....	\$					
Compensation Ins	\$					
Trucking	\$					
Builders' Use of Water	\$					
Total \$.....							

22' 3" 20' 9" 77' 9" old measurements

103 Broadway
9/25/30

Labor and Material Report

19

Broad St.
Old Fielding Property

Main Elev of Main at tap

Gate at ● ● Gate at

● Curb Box

It is shut off
The measurement of
the curb box is measured
in from these lots

Old Fielding Property

It is shut off. The measurement of the curb box is measured in from these lots (?)