

Labor and Materials

1	Lead Connection	3.20	\$	3.20
1	Curb Cock	95	\$	95
1	Service Box (Short 3½ x 4½)		\$	
8	Old returned (Long 4½ x 5½ Buffalo)		\$	
8	¾ in. G. I. Pipe at cop	1.76	\$	1.76
	Nipples in. at		\$	
	Bushings to in. at		\$	
	Red'g Coup to in. at		\$	
	Inc'g Coup to in. at		\$	
	Union in. at		\$	
	Meter in. at		\$	
	Cu. Yds. Br. Stone at		\$	
	Cu. Yds. Sand at		\$	
	Bags Cement at		\$	
	Paving Brick { Mack Red Asphalt } at		\$	
2	Hrs. Foreman at	1.25	\$	1.25
8.7	Hrs. Common Labor at	3.35	\$	3.35
	Hrs. Mason at		\$	
	Hrs.		\$	
	Hrs.		\$	
No	Builders' Use of Water		\$	
	Truck	1.00	\$	1.00
			\$	
			\$	
			\$	
			\$	
	Total	14.69	\$	14.69

Labor and Material Report

19

88 Broad St. Mission St. Side.



RAZED

16" Main

Elev. of Main at tap

Gate at ●

● Gate at

