

Labor and Materials

1	Copper	Connection	3/4"	\$	3.20
	Lead				
1	Curb	Cock Valve	3/4" in.	\$	1.00
		T.S. & V.			
	Service Box	Short 3 1/2 x 4 1/2		\$	1.30
	Old returned	Long 4 1/2 x 5 1/2			
		Buff. or Rdway			
3/4	Ft.	3/4 in.	Copper Galv. Iron Cast Iron	Pipe at	\$ 7.48
	Nipples	in. at		\$	
	Bushings	to in. at		\$	
1	Red'g Pipe	Couplings	3/4" to Brass	in. at	\$ 1.50
	Union	in. at		\$	
	Meter	in. at		\$	
	Lbs. Br. Stone	at		\$	
	Lbs. Sand	at		\$	
	Bags Cement	at		\$	
	Paving Brick	Mack Red Asphalt	at	\$	
	Lead Joints	at		\$	
	Leadite Joints	at		\$	
6	Hrs. Foreman	at	6.2.5	\$	3.75
2.5	Hrs. Common Labor	at	50	\$	12.50
	Hrs. Common Labor	at		\$	
	Hrs. Mason	at		\$	
	Hrs. Mason's Helper	at		\$	
	Hrs. Compressor	at		\$	
	Compensation Ins.			\$.42
	Trucking			\$	1.00
	Builders' Use of Water			\$	
				Total	\$ 30.80

Labor and Material Report

19

#108
3/4" Loh at 86 Broad at
9/30/84



RAZED

Main Elev. of Main at tap
Gate at ● Gate at ●

● Curb Box

106 + 108
#84 + 86
are on bare shif
#108 - Shutoff in
Cellar - 3-15-72